

East Germany

FDD Abstract of [redacted]

25X1A

- LIST OF SOVIET AIRCRAFT ACCESSORIES; No of pages - 2; Russian; Date - 1951 ?

25X1A

| | | |
|-----|---|----|
| 1. | Artificial horizon, AGP-2 | 17 |
| 2. | Artificial horizon, AGP-1 | 1 |
| 3. | Air temperature gauge, with wire 3.3 | 5 |
| 4. | Gasoline gauge, SRE-1086 | 4 |
| 5. | Gasoline gauge, BE-490 | 2 |
| 6. | Compass, KI-4 | 1 |
| 7. | Oil pressure gauge, with intake | 5 |
| 8. | Tachometer, TE-44 | 5 |
| 9. | Tachometer, up to 300 rpm | 5 |
| 10. | Tachometer dial, TE-22 | 11 |
| 11. | TME-41 <u>(Water temperature gauge, TME-41)</u> | 19 |
| 12. | Pitot tubes | 2 |
| 13. | Speed indicator, US-800 | 16 |
| 14. | Gasoline indicator dial, BE-490 | 2 |
| 15. | Gasoline indicator dial, BE-499 | 4 |
| 16. | Gasoline gauge, UB | 2 |
| 17. | Tachometer dial, TE-44 | 3 |
| 18. | Voltampere meter, VA-140 | 6 |
| 19. | Voltampere meter, VA-240 | 2 |
| 22. | Climb indicator, VR-30 | 7 |
| 23. | Climb indicator, VR-10 | 1 |

Return to CIA Library

SECRET
SECURITY INFORMATION

Continue:

| | | |
|-----|--|----|
| 24. | Altimeter, 2 arrows, calibrated for 12 units | 8 |
| 25. | Indicator, 3 arrows, 3.3 m | - |
| 26. | Vacuum gauge, MV-16 | 2 |
| 27. | Air pressure gauge, up to 12 atmospheres | 2 |
| 28. | Air pressure gauge, up to 80 atmospheres | 2 |
| 29. | Compass, KI-11 | 5 |
| 30. | Gasoline gauge, SBE-1086 | 13 |
| 31. | Indicator (datchik)- SB-1080 | 2 |
| 32. | Air pressure gauge, up to 250 | 4 |
| 33. | Air pressure gauge, up to 60 | 1 |
| 34. | Thermometer, TME-41, oil | 2 |
| 35. | Wing flap indicator, UZ-40 | 2 |
| 36. | Flap position indicator, UZP-40 | 7 |
| 37. | Filter, SF-1A | 1 |
| 38. | Speed indicator, US-350 | 1 |
| 39. | Gasoline pressure gauge | 1 |
| 40. | Indicator (datchik), BE-490 | 7 |
| 41. | Tachometer, TE-22 | 10 |
| 42. | [No entry] | |

Complete translation.

Foreign document or microfilm of it (C 12447) is available from CIA
library: [redacted]

25X1A

25X1A

6 Nov 1952

SECRET
SECURITY INFORMATION

East Germany

FDD Abstract of

25X1A

LIST OF SOVIET AIRCRAFT ACCESSORIES; No of pages - 2; Russian; Date - 1951 ?

25X1X

25X1A

| | | |
|-----|--|----|
| 1. | Artificial horizon, AGP-2 | 17 |
| 2. | Artificial horizon, AGP-1 | 1 |
| 3. | Air temperature gauge, with wire 3.3 | 5 |
| 4. | Gasoline gauge, SBE-1086 | 4 |
| 5. | Gasoline gauge, BE-490 | 2 |
| 6. | Compass, KI-4 | 1 |
| 7. | Oil pressure gauge, with intake | 5 |
| 8. | Tachometer, TE-44 | 5 |
| 9. | Tachometer, up to 300 rpm | 5 |
| 10. | Tachometer dial, TE-22 | 11 |
| 11. | TME-41 <u>Water temperature gauge, TME-417</u> | 19 |
| 12. | Pitot tubes | 2 |
| 13. | Speed indicator, US-800 | 16 |
| 14. | Gasoline indicator dial, BE-490 | 2 |
| 15. | Gasoline indicator dial, BE-499 | 4 |
| 16. | Gasoline gauge, UB | 2 |
| 17. | Tachometer dial, TE-44 | 3 |
| 18. | Voltampere meter, VA-140 | 6 |
| 19. | Voltampere meter, VA-240 | 2 |
| 22. | Climb indicator, VR-30 | 7 |
| 23. | Climb indicator, VR-10 | 1 |

**SECRET
SECURITY INFORMATION**

Continue:

| | |
|--|----|
| 24. Altimeter, 2 arrows, calibrated for 12 units | 8 |
| 25. Indicator, 3 arrows, 3.3 m | - |
| 26. Vacuum gauge, WV-16 | 2 |
| 27. Air pressure gauge, up to 12 atmospheres | 2 |
| 28. Air pressure gauge, up to 80 atmospheres | 2 |
| 29. Compass, XI-11 | 5 |
| 30. Gasoline gauge, SEP-1086 | 13 |
| 31. Indicator (datchik)- SB-1080 | 2 |
| 32. Air pressure gauge, up to 250 | 4 |
| 33. Air pressure gauge, up to 60 | 1 |
| 34. Thermometer, TME-41, oil | 2 |
| 35. Wing flap indicator, UZ-40 | 2 |
| 36. Flap position indicator, UZF-40 | 7 |
| 37. Filter, SF-1A | 1 |
| 38. Speed indicator, US-350 | 1 |
| 39. Gasoline pressure gauge | 1 |
| 40. Indicator (datchik), BE-490 | 7 |
| 41. Tachometer, TE-22 | 20 |
| 42. <u>No entry</u> | |

Complete translation.

25X1A
25X1A

Foreign document or microfilm of it [] is available from CIA
library: []

25X1A

[] 6 Nov 1952

SECRET
SECURITY INFORMATION

INTELLOFAX 29

CLASSIFICATION SECRET

SECURITY INFORMATION

CENTRAL INTELLIGENCE AGENCY

REPORT NO. [REDACTED]

0 12447 25X1A

INFORMATION REPORT

CD NO.

COUNTRY

East Germany


DATE DISTR. 16 Oct. 1952

SUBJECT

List of Soviet Aircraft Accessories


NO. OF PAGES 1

PLACE ACQUIRED



NO. OF ENCLS. 1 (2 photostats)
(LISTED BELOW)

DATE OF INFO:
ACQUIRED



SUPPLEMENT TO
REPORT NO.

25X1X

[Large redacted area]
DO NOT DETACH

1. Enclosed is a photostat of a document in Russian found at the deactivated air-force depot at Falkensee. The document contains a list of various aircraft accessories, and is believed to be a stock record account.
2. This document is sent you for retention.

May 19 1952
CIA RDP129A00900063
OSI/C

25X1A

CLASSIFICATION SECRET

| Состав оборудования | | штук | з |
|---------------------|------------------------|-------------------|-----|
| 1. | Манометр | 1 | 1 |
| 2. | - " | МТК | 1 |
| 3. | Стрелотермометр с проб | 3,3 | 5 |
| 4. | Бензиномер | СБУ-1086 | 4 |
| 5. | - " | БУ-490 | 2 |
| 6. | Холост | ХЦ-4 | 1 |
| 7. | Манометр масла | стриж | 5 |
| 8. | Тахометр | МЭ-44 | 5 |
| 9. | - " | го 300 об/м | 5 |
| 10. | ЧК | МЭ-22 | 11. |
| 11. | МДК-41 | 609 | 13 |
| 12. | Трубка питье | | 2 |
| 13. | Указатель скорости | УС-800 | 10 |
| 14. | - " | Бензиномер БУ-490 | 2 |
| 15. | - " | - " БУ-499 | 4 |
| 16. | Бензиномер | УБ | 2 |
| 17. | Указатель тахометра | Т-44-3 | |
| 18. | Воздуштепериметр | ВЗР-140 | 6 |
| 19. | - " | ВЗР-240 | 2 |
| 20. | Вакууметр | ВЗР-30 | 2 |
| 21. | - " | ВЗР-10 | 1 |
| 22. | Вакууметр 2-сторонний | го-12 | 8 |

25X1A

Approved For Release 2002/08/15 : CIA-RDP83-00415R012900090006-3 .

SECRET

SECRET

Approved For Release 2002/08/15 : CIA-RDP83-00415R012900090006-3

| | | | |
|---|-----------|-----------------------------|--------------|
| 25. | Указатель | 32 | 33 |
| Approved For Release 2002/08/15 : CIA-RDP85-0415R012900090006-3 | | | |
| 26. | Манометр | МВ-16 | = 2 |
| 27. | Манометр | Бозука | го 12 кг = 2 |
| 28. | " | " | 99.88 км = 2 |
| 29. | Компас | Ку-11 | = 5 |
| 30. | Декомпакт | СДЗ-4086 | = 13 |
| 31. | Датчик | СД | 1080 = 2 |
| 32. | Манометр | Бозука | го 250 = 4 |
| 33. | " | " | го 60 = 1 |
| 34. | Манометр | МД-412-412а | = 2 |
| 35. | Указатель | заправки УЗ-40 | = 2 |
| 36. | Указатель | нахождения заправки УЗ-5-40 | = 3 |
| 37. | Руль | СР-101 | = 1 |
| 38. | Указатель | прогрессии УС-350 | = 1 |
| 39. | Манометр | Бозука | = 1 |
| 40. | Датчик | СД-4-490 | = 2 |
| 41. | Манометр | МД-22 | = 10 |
| 42. | " | | |

25X1A

Approved For Release 2002/08/15 : CIA-RDP83-00415R012900090Q06-3

SECRET

THIS IS AN ENCLOSURE TO
DO NOT DETACH

SECRET

Approved For Release 2002/08/15 : CIA-RDP83-00415R012900090006-3